

LARK ENGG. CO. (INDIA) PVT. LTD

I.T.I SASOULI ROAD, YAMUNA NAGAR, PH. 91-1732-257685, 259685

SERVICE/ VISIT REPORT

	RVICE/ VISIT REPORT Format: LEC/P-38
roject Name: M/S SURYA IDUSTRIES,	Project Location: Muzaffarnagar, Uttar Pradesh
Feed Plant:	Plant: 2-3 TPH Pellet Feed Plant (Poultry & Cattle)
Plant operation:	If Automatic:
Type of Call	Maintenauce
lame of Service Person (Lark epresentative)	Dinesh Kumar
Arrival at Site (Date / Time)	10! 40 AM
Departure from Site (Date / Time)	U: 0. PM
Customer Concern	(1) Palate mill motor triping Problam
	again again.
	2) Harrarmill feeder not working in and
	alito mode
Action Taken	O. Problam Surch Fult found in
	State Rely Fulty and one contracto
	Connotion lose change Rely and
	tight all connection
	2) Hamarmin feeder drive Rur in local mode check
	local mode chang mode and check
	Parameter ox
Job Completion Status	Complent Solution done
Performance after completion of Job	Satisfied ()
General feedback/ comments	
	Signature of Service Person (Lark

Client Signature with stamp Representative)

Note: During Service, you have to arrange lodging facility (free of cost) to our representative during their stay at your site.